

Block side plates
– check for wear
on inside edges

Check for excessive
movement of sheave
on bearing

Check for signs
of elongation or
distortion at
fixing point

Check for any
distortion to shackle

