

A close-up photograph of a boat's pulley system. A black pulley with three white sheaves is suspended by a white rope with yellow and blue flecks. Below it, a silver metal traveller is mounted on a stainless steel track. The traveller has two black pulleys on either side, through which a white rope with blue flecks passes. The background is a light blue-grey surface. Four white callout boxes with black text and dotted lines pointing to specific parts of the system are overlaid on the image.

Flush cleats with fresh water – check for broken return springs

Check sheaves for damage and excessive wear

Check traveller end caps for signs of damage

Flush underside of traveller with fresh water to dislodge salt crystals